




eROV - Thruster drives

Omron 3G3MX2A4075V1 480V


Modified defaults

1	Remove "shortening Bar P24 - PSC "	
2	Link "FI - SC"	
3	Link "P24 - MC"	
4	F002	1.00
5	F202	1.00
6	F003	1.00
7	F203	1.00
8	F004	01
9	A001	01
10	A002	01
11	A004	75.0
12	A005	02
13	A012	75.00
14	A041	01
15	A241	01
16	A044	01
17	B001	02
18	B002	10
19	B008	02
20	C028	01
21	H003	11



2-2 Wiring

Connection Diagram



Note 1: Connect a single-phase 200 V AC input to terminals L1 and N.
 Note 2: Factory default settings for relay output are NC contact for MA and NO contact for MB.